PROPERTY LOCATED AT: 3 FIRE Lane 432 Andoyes, ME 04216

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

	SECTION I – WATER SUPPLY
TYPE OF SYSTE	EM: Public Private Seasonal Unknown Drilled Dug Other Unknown
MALFUNCTION	IS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?
	Pump (if any): Unknown
	Quantity:
	Quality: \Box Yes X No \Box Unknown
	If Yes to any question, please explain in the comment section below or with attachment.
WATER TEST:	Have you had the water tested?
	If Yes, Date of most recent test: Are test results available? 🕅 Yes 🗌 No
	To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation?
	If Yes, are test results available? \Box No
	What steps were taken to remedy the problem? Installed filtration system Dec 2020
IF PRIVATE: (Str	rike Section if Not Applicable):
INSTALLATI	ION: Location: Back yard
	Installed by: UNKNOWN
,	Date of Installation: estimate 2003 - 2004 (fine of home construction
USE:	Number of persons currently using system:
	Does system supply water for more than one household? Yes X No Unknown
Comments:	
Source of Section	I information: Current owner
Buyer Initials	Page 1 of 7 Seller Initials
Kersey Real Estate, 506 West Side Michael Kersey	Road Weld ME 04285 Phone: 2075852411 Fax: D Orino Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

YPE OF SYSTEM: Public Quasi-Public	Unknown
F PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable): Have you had the sewer line inspected? If Yes, what results: Have you experienced any problems such as line or other malfunctions?	
What steps were taken to remedy the problem?	
F PRIVATE (Strike Section if Not Applicable):	
Tank Type: Concrete Metal Unknown Other	
Location: Front of house, risers installed 2020 0	\mathbf{R} \Box $\mathbf{U}\mathbf{n}\mathbf{k}\mathbf{n}\mathbf{o}\mathbf{w}\mathbf{n}$
Date installed: ~ 2003 Date last pumped: Aug 2020 Name of pumping company	DOYON Weste
Date installed: ~ 2003 Date last pumped: $\frac{100}{403}$ 2020 Name of pumping company Have you experienced any malfunctions?	[] Yes X No
If Yes, give the date and describe the problem:	
Date of last servicing of tank: 6/09/2020 Name of company servicing tank: Western	Mara Spotic Taspedu
Leach Field: X Yes	No Unknown
If Yes, Location: Front LAWN	
Date of installation of leach field: 2003 Installed by: UNKNOWN	
Date of last servicing of leach field: UMKIWM Company servicing leach field:	
Have you experienced any malfunctions?	🗌 Yes 🕅 No
If Yes, give the date and describe the problem and what steps were taken to remedy:	
Do you have records of the design indicating the # of bedrooms the system was designed for	or? 🗌 Yes 🕅 No
If Yes, are they available?	🗌 Yes 🕅 No
Is System located in a Shoreland Zone?	No 🗌 Unknown
omments:	

Buyer Initials

Seller Initials

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

D Orino

PROPERTY LOCATED AT: 3 FIRELANE 432 Andover ME 04216

SEC	TION III – HEATIN	NG SYSTEM(S)/HEA	TING SOURCES(S	S)			
Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4			
TYPE(S)	FHA Propune		ement) Pellet stove				
Age of system(s) or source(s)	2019	2020	202	-Coloran >)			
Name of company that services	P	1/1	NI /A				
system(s) or source(s)	Community Energy	N/A	N/A				
Date of most recent service call Annual consumption per system	6/21/20210	N/A	N/A				
or source (i.e., gallons, kilowatt	1100 lloss /	(60 6255)					
hours, cords)	400 gallons/year	3 metric tous	Metricton				
Malfunction per system(s) or		2022					
source(s) within past 2 years	None	Replaced blower	None				
Other pertinent information							
8							
Are there fuel supply line	s?		X Yes	No Unknown			
Are any buried?			Yes	No 🗌 Unknown			
Are all sleeved?				No Unknown			
Chimney(s):							
If Yes, are they lined:				No Unknown			
	source vented through			No Unknown			
Had a chimney fire: .							
				No Unknown			
Has chimney(s) been inspected? Yes Ves Unknown							
If Yes, date:							
Date chimney(s) last c	cleaned:			DO			
Direct/Power Vent(s): Yes Has vent(s) been inspected? Yes							
Has vent(s) been inspected?							
If Yes, date:							
Comments: 2 pellet stores							
Source of Section III information: CUTTENT OWNER							
		– HAZARDOUS MA	TERIAL				
The licensee is disclosing							
A. UNDERGROUND	STORAGE TANKS	- Are there now on	hamed here area have				
storage tanks on the prope	ertv?	- Are more now, or	1	A			
				No 🗌 Unknown			
If Yes, are tanks in current use?							
If no longer in use, how long have they been out of service?							
Are tanks registered with	DEP?	andoned according to	DEP?	No Unknown			
Age of tank(s):				No Unknown			
agation		e of tank(s):					
Buyer Initials		Page 3 of 7 S	eller Initials				
	Lone Wolf Transactions (zipForm Edition						
				D Orino			

PROPERTY I	LOCATED AT:
-------------------	-------------

3 Fire Lone 432 Andover ME 04216		3	Fire	Lane	432	Andover	ME	04216
----------------------------------	--	---	------	------	-----	---------	----	-------

What materials are, or were, stored in the tank(s)?		
Have you experienced any problems such as leakage:		No Unknown
Comments:		
Source of information:		
B. ASBESTOS – Is there now or has there been asbestos:		
As insulation on the heating system pipes or duct work?	Yes	No 🗌 Unknown
In the ceilings?		No Unknown
In the siding?		No Unknown
In the roofing shingles?		No Unknown
In flooring tiles?		No Unknown
Other:		No Unknown
Comments:		
Source of information:		
C. RADON/AIR - Current or previously existing:		
Has the property been tested?	Yes	🗌 No 🔀 Unknown
If Yes: Date: By:		
Results:		
If applicable, what remedial steps were taken?		
Has the property been tested since remedial steps?	Yes	No Unknown
Are test results available?		
Results/Comments:		
Source of information:		
D. RADON/WATER - Current or previously existing:		5
Has the property been tested?	Yes	🗌 No 🕅 Unknown
If Yes: Date: By:		
Results:		
If applicable, what remedial steps were taken?		
Has the property been tested since remedial steps?	Yes	No Unknown
Are test results available?		□ No
Results/Comments:		
Source of information:		
E. METHAMPHETAMINE - Current or previously existing:	Yes	No Unknown
Comments:		<u>/</u>
Source of information:		
Buyer Initials Page 4 of 7	Seller Initials	
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dall	as, TX 75201 <u>www.lwolf.com</u>	D Orino

PROPERTY LOCATED AT:	3	Fire Lane	432	Andover	ME	04216

F. LEAD-BASED PAINT/PAINT HAZARDS — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)
Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
If Yes, describe location and basis for determination:
Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes No
If Yes, describe:
Are you aware of any cracking, peeling or flaking paint?
Comments:
Source of information:
G. OTHER HAZARDOUS MATERIALS - Current or previously existing:
TOXIC MATERIAL:
LAND FILL:
RADIOACTIVE MATERIAL:
Other:
Source of information: CUrvent owner
Buyers are encouraged to seek information from professionals regarding any specific issue or concern.
SECTION V – GENERAL INFORMATION
Is the property subject to or have the benefit of any encroachments, proceeding the rest in the second

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of
first refusal, life estates, private ways, trails, homeowner associations (including condominiums
and PUD's) or restrictive covenants? I Yes Xes No Unknown
If Yes, explain:
Source of information:
Is access by means of a way owned and maintained by the State, a county, or a municipality
over which the public has a right to pass?
If No, who is responsible for maintenance?
Road Association Name (if known):

Buyer Initials _____ Page 5 of 7 Seller Initials D

D Orino

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

PROPERTY LOCATED AT: 3 FIRE LONG 432 Andover ME 04216

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?......

If Yes, explain:
water filtration system photovoltaics wind turbines). Type: PCA David the alter filtration
Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: <u>Propane tanks (Community</u> Year Principal Structure Built: <u>2003</u> Energy owned
What year did Seller acquire property? 2020
Roof: Year Shingles/Other Installed: 2003
Water, moisture or leakage: $N \partial$
Foundation/Basement:
Prior water, moisture or leakage?
Prior water, moisture or leakage?
Mold: Has the property ever been tested for mold?
If Yes, are test results available?
Comments:
Electrical: Fuses Circuit Breaker Other: Unknown
Comments:
Has all or a portion of the property been surveyed?
If Yes, is the survey available?
Manufactured Housing – Is the residence a:
Mobile Home Yes X No 🗌 Unknown
Modular
Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
\square Yes \square No \square Unknown
Comments:
KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may
have an adverse impact on health/safety: None
Comments:
Comments:
Buyer Initials Page 6 of 7 Seller Initials Poly PolyPOly

PROPERTY LOCATED AT: 3 FIRE LANCe 432 Andover, ME 04216

SECTION VI – ADDITIONAL INFORMATION
Upon initial testing of well water, Filtration system added
to address ivon, Manganese, & choliform bacteria. Retest
Shined issues adequately addressed through filtration,
Testing attached. 0

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE:

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

SELLER	DATE	SELLER	DATE
SELLER	DATE	SELLER	DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER		DATE	BUYER	DATE
BUYER		DATE	BUYER	DATE
REALTOR® Maine A	Page 7 of 7 Maine Association of REALTORS®/Copyright © 2022. All Rights Reserved. Revised 2022. Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com			состан исление состан исление состание D Orino